

5253 7474

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

<b>PERMIT NO.</b>	<b>LOCATION</b> 4439 - 6th Avenue
<b>DATE</b>	<b>PURPOSE</b> Wreck 1-family dwelling
	<b>OWNER</b> William H. Thompson 811 - F St.
<b>ZONE</b>	<b>ARCH'T</b>
	<b>CONT'R</b>

<b>VAL.</b>	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>	<b>PHONE (O) (C)</b>
<b>FORM</b>				
<b>JOIST</b>		Condemned by Building Division		
<b>FRAME</b>				
<b>SHEET NOCK</b>				
<b>FINAL</b>				

<b>DATE</b>	<b>SPECIAL CONDITIONS OF WORK — REMARKS</b>
<b>COMPLETE AND OK</b>	<b>INSPECTOR</b>