

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-3794</i>	LOCATION <i>911-53rd Ave</i>
DATE <i>9-1-39</i>	PURPOSE <i>Erect new dwlg.</i>
ZONE	OWNER <i>Gen. McShuffe</i>
	ARCH'T.
	CONTR. <i>B-M. Phelps</i>

VAL. <i>42000</i>	STORIES <i>1</i>	ROOMS	APTS.	SIZE
-------------------	---------------------	-------	-------	------

LIGHT SHAFTS	ELEVATOR SHAFTS <i>area</i>
VENT SHAFTS	BOILER ROOMS <i>1232'</i>
OWNER'S INSPECTOR	SPRINKLER SYSTEM <i>@ 35'</i>
LATH	GAS VENTS
FIRE ESCAPES	CHIMNEYS
STAND PIPES	SKYLIGHTS

DATE	CONDITION OF WORK - REMARKS	
9-13-39	1 st - Lamp	Frames of Quiter
'10-25-39	2 " "	Frames " Quiter
11-8-39	3 " "	Lack Int & Ext " Quiter
	<p data-bbox="280 1005 437 1052">COMPLETE AND O. K.</p> <p data-bbox="1280 1023 1445 1052">INSPECTOR</p>	