

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|-----------------------------|--|
| PERMIT NO. <i>A-6938</i> | LOCATION <i>1614 1/2 - M Street -</i> |
| DATE <i>9/13/37</i> | PURPOSE <i>Repairs to residence</i> |
| ZONE | OWNER <i>G. M. Henderson.</i> |
| | ARCH'T. |
| | CONT'R. <i>Owner</i> |

| | | | | |
|--------------------|---------|-------|-------|------|
| VAL. <i>190.00</i> | STORIES | ROOMS | APTS. | SIZE |
|--------------------|---------|-------|-------|------|

| | |
|-------------------|------------------|
| LIGHT SHAFTS | ELEVATOR SHAFTS |
| VENT SHAFTS | BOILER ROOMS |
| OWNER'S INSPECTOR | SPRINKLER SYSTEM |
| LATH | GAS VENTS |
| FIRE ESCAPES | CHIMNEYS |
| STAND PIPES | SKYLIGHTS |

| DATE | CONDITION OF WORK-REMARKS |
|-----------------------|--|
| 9/21/37 | 2 ND / NSP. Frame for remodeling Apt on 2 ND Floor |
| | O.K. AW Campbell |
| | |
| | |
| | |
| | |
| COMPLETE AND O. K. | INSPECTOR |