

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-1117</i>	LOCATION <i>858-54<sup>th</sup> St.</i>
DATE <i>11/2/37</i>	PURPOSE <i>Make additions to rear porch</i>
OWNER <i>Mrs E. Smith</i>	PHONES
ARCH'T <i>Owner</i>	
CONT-R	

VAL. <i>200.00</i>	STORIES	ROOMS	APTS.	SIZE
--------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
1/25/34	Made inspection of rear porch enclosed with screen & sash. Frame OK. H.W. Campbell
	COMPLETE AND O. K. <span style="float: right;">INSPECTOR</span>