

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-1630</i>	LOCATION <i>3541-52nd St</i>			
DATE <i>5/9/34</i>	PURPOSE <i>Make alterations to dwell.</i>			
OWNER <i>J. Cortez</i>	ARCH'T			
ZONE <i>400⁰⁰</i>	CONT'R <i>Owner</i>			
VAL <i>250⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
5/18/34	1 ST WSP. Frame for 1 Room Basement Addition to rear of dwlg. in place ^{OK} A.W. Campbell
5/21/34	2 ND WSP. (PARTIAL FRAME) ^{OK} A.W. Campbell
6/13/34	2 ND WSP. Frame for Addition ^{OK} A.W. Campbell
6/13/34	3 RD WSP. INT. PART " " ^{OK} A.W. Campbell.
8/15/34	4 TH WSP. Additions to Dwlg. Completed ^{OK} A.W. Campbell
8/15/34	COMPLETE AND O.K. <i>Alden W. Campbell</i> INSPECTOR