

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

600

TYPE BUILDINGS

R44 F844

PERMIT NO. C-9217	LOCATION 1200 18th Street			
DATE 7-7-58	PURPOSE Repair stairs & dry rot			
ZONE	OWNER Munk			
	ARCH'T			
	CONT'R C. Va nina			
VAL. \$675.00	STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	INSPECTOR		
FORM				
JOIST				
FRAME				
LATH				
FINAL				

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100



DATE	SPECIAL CONDITIONS OF WORK—REMARKS
COMPLETE AND OK	INSPECTOR

