

*R317 F 399*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$6.00**

**TYPE BUILDINGS**

PERMIT NO.					
H-4731	LOCATION	3325 - 33rd Street A-1 (27)			
DATE	PURPOSE	Repair pest damage to dwelling			
Dec. 16-71	OWNER	F.H.A. 801 - I Street			
ZONE	ARCH'T				
R-1	CONT'R	Atox Termite Co. 5831 - Rosebud Ln.			
VAL. \$500.		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP		PHONE (O) (C)
FORM	<i>12-23-71</i>	<i>Sachato</i>			331 2633
JOIST					
FRAME					
SHEET ROCK					
FINAL	<i>1-10-72</i>	<i>Dana Fuller</i>			

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	COMPLETE AND OK

INSPECTOR