

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>1-6083</i>	LOCATION <i>2911-35th St</i>
DATE <i>4/8/37</i>	PURPOSE <i>Repairs - Restaurant Bldg</i>
ZONE	OWNER <i>Sanford</i>
	ARCHT.
	CONTR. <i>Elton Blair</i>

VAL. <i>300</i>	STORIES	ROOMS	APTS.	SIZE
-----------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE

CONDITION OF WORK-REMARKS

5/10.37

Found 200 Pavers

COMPLETE
AND O. K.

INSPECTOR