

2210 7339-343

Lot 79		BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD			\$61.00
South Land Park Hills TYPE BUILDINGS #11					
PERMIT NO. F-6451		LOCATION		1221 - 58th Avenue	A-3
DATE Feb 15-67		PURPOSE		Const. dwl. & att. gar.	
		OWNER		Ken Kamada 825-361 Air Drv	
ZONE R-1		ARCH'T			
		CONT'R		Owner	
VAL. \$17,500.		STORIES	ROOMS	APTS.	SIZE 450-gar. 1856 sq. ft.
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)	
FORM	2-24-67	Hammons			
JOIST	3-3-67	Hammons			
FRAME	4-6-67	Chapin			
SHEET ROCK	4-13-67	Chapin			
FINAL	6-30-67	Chapin			

1. This form is to be filled out by the building inspector. It is not to be filled out by the contractor or other interested parties.

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
2-16-67	P. Frame - to replace fourth &
	discharge not right Chicago
4-4-67	P. Frame - 2 to tie post & pulley
	in gas. Backing at shown & work
	directed Chicago
4-11-67	P. Frame - to gas & work directed - to load
	parts in S. R. Frame must be 3"
	backing Chicago
	<p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p>