

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>4-2469</i>		LOCATION <i>5140 - T.P.T.</i>			
DATE <i>11/19/37</i>		PURPOSE <i>Erect new dwlg - garage</i>			
ZONE <i>1-7am</i>		OWNER <i>E. R. Loranham</i>			
		ARCH'T.			
		CONTR. <i>Owner</i>			
VAL.	<i>2800<sup>±</sup></i>	STORIES <i>1</i>	ROOMS <i>4</i>	APTS.	SIZE
LIGHT SHAFTS				ELEVATOR SHAFTS	<i>area</i>
VENT SHAFTS				BOILER ROOMS	<i>936.±</i>
OWNER'S INSPECTOR				SPRINKLER SYSTEM	
LATH				GAS VENTS	
FIRE ESCAPES				CHIMNEYS	
STAND PIPES				SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS	
1-2-38	1	Lump Form of Rupture
1-17-38	2 <sup>nd</sup>	Lump Form of Rupture
2-3-38	3	Lump ~ Rupture

COMPLETE  
AND O. K.

INSPECTOR