

**BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD**

**TYPE VII BUILDINGS**

<b>PERMIT NO.</b> <i>4189</i>	<b>LOCATION</b> <i>1600 S. [unclear]</i>		
<b>DATE</b> <i>15</i>	<b>PURPOSE</b> <i>Add open lunch counter</i>	<b>ROOMS</b>	<b>APTS.</b>
<b>ZONE</b> <i>SACRA</i>	<b>OWNER</b> <i>Scheitel &amp; Kiefe</i>		<b>PHONE</b>
<b>VAL.</b> <i>450 -</i>	<b>ARCH'T</b>		<b>CONT'R</b> <i>W. H. Sandmeyer</i>
<b>FOUNDATION</b>	<b>STORY</b>	<b>BSMT</b>	<b>STORIES</b>

FOUNDATION	STORY	BSMT	1	2	3	ROOF	Chimneys	Cement Tests
Ex Wall	Joists							
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand. Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
3/25/29	1 <sup>ST</sup> /N.S.P. Extension of Cement Floor <sup>OK</sup> A.H. Campbell
	2 <sup>ND</sup> /N.S.P. Frame for Addition to Lunch Stand <sup>OK</sup> A.H. Campbell
	<p data-bbox="336 970 520 1029">COMPLETED AND O. K.</p> <p data-bbox="1302 1005 1470 1029">INSPECTOR</p>