

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. NO CHARGE (REPAIRS) DATE MAY 25th		LOCATION 374 U. ST.	
PURPOSE Replaster 3 Rms of Dully		PHONES	
OWNER JOHN FONTES			
ARCH'T			
CONT-R OWNER			
ZONE General Commercial	VAL.	STORIES 75⁰⁰	ROOMS 1
		APTS. 1	SIZE.

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE

CONDITION OF WORK-REMARKS

**COMPLETE
AND O.K.**

INSPECTOR