

RECORD OF SUBSEQUENT PERMITS ISSUED

DATE	TYPE OF PERMIT AND VALUATION	PERMIT NO. AND FEE	NATURE OF WORK	PRESENT OWNER AND ADDRESS	CONTRACTOR & ADDRESS	FINALED BY	DATE
9-17-80	RPE \$5000.00 <i>H-4587 \$122.00</i>	H-6859	Termite Repair Dwl	J. Rochick Same	Owner	<i>William</i>	<i>6/26/81</i> NO FINAL INSPECTION CALIF. INSPECTION PERMITEE
2-12-81	Bldg. \$329.00	H10692, \$20.00	Bldg. walking closet.	Domingo Rodrick 173 40th Street	Owner 173 40th Street	<i>William</i>	<i>8/13/85</i>
5-21-81	ME \$3250.	I-2011 \$105.	Install heat pump.	Domingo Rodrick 173 40th St.	A&P Heating & cooling 6423 Elvas Ave.	<i>William</i>	<i>8/14/81</i>
2/10/82	BE \$1848.	I-10737 \$55.	Const. garage	T. Rodrich same	Owner	<i>William</i> <i>Nasca</i>	<i>8/14/81</i> <i>6/17/82</i>

MICROFILM RECORD

PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.	PERMIT NO.	REEL AND FRAME NOS.
H-6859	<i>R639F597</i>	<i>H6859</i>	<i>10A3 361</i>		
H-10692	<i>R660 F539-541</i>				
I-2011	<i>R718F289</i>				
<i>I-2011</i>					
I-10737R	R711F103-105				
<i>I-10737R</i>					
	<i>R870 F336</i>				
<i>H10692</i>					