

Lot 869 BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD \$42.50

Northgate#6

TYPE BUILDINGS

R91 7566
R86 7528-535

| | | | | |
|---------------------|---------------------------------------------------|-------------|--------------------------------|------|
| PERMIT NO. E-166 | LOCATION 1113 W. El Camino Ave. A-2 | | | |
| DATE 11/21/61 | PURPOSE Dwelling & att garage Plan 600/60 | | | |
| ZONE R-1 | OWNER ElCamino Partners 1201 W. ElCamino | | | |
| | ARCH'T | | | |
| | CONT'R Du Brow & Pleman 1201 W. Elcamino WA 26897 | | | |
| VAL. \$15,600. | STORIES 2 | ROOMS 6 | APTS. 462 Gar. 968 S. F. | SIZE |
| INSP. | DATE | INSPECTOR | | |
| FORM | 12-23-61 | Julle | | |
| JOIST | | | | |
| FRAME | 3-22-62 | Dahlsto | | |
| LATH | 3-29-62 | Dahlsto | | |
| FINAL | 5-28-62 | M. Callaway | | |

| DATE | SPECIAL CONDITIONS OF WORK—REMARKS |
|---------|------------------------------------------------------------------------|
| 1-12-62 | Red Top Barbed |
| 3-8-62 | Must replace all utility lumber used for any shoring |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | <p>COMPLETE AND OK</p> <p style="text-align: right;">INSPECTOR</p> |