

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>No Charge</i>	LOCATION <i>1900 P. St.</i>
DATE <i>June 12 1933</i>	PURPOSE <i>Change Windows to Door for Side Entrance Change Location of Sign</i>
ZONE <i>General Commercial</i>	OWNER <i>SAM. FILPI</i>
	ARCH'T
	CONT-R <i>OWNER</i>
	PHONES <i>Install T &amp; G. Partitions in rear of store</i>

VAL. <i>50<sup>00</sup></i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE
-----------------------------	------------------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK—REMARKS
6/17/33	<p>Save Corner &amp; Store No Change Permitted in making  small alterations &amp; repairs. Changing 1 Window  to Door with Curtains on side. Changing location  of quilt and metaling T &amp; B. Partitions as necessary  store &amp; minor repairs OK A W Campbell</p>
COMPLETE AND O. K.	INSPECTOR