

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

2627 D St.

PERMIT NO. <i>6893</i>	LOCATION		
DATE <i>9/13/30</i>	PURPOSE <i>Roof</i>	ROOMS	APTS.
ZONE <i>Multiple-Family</i>	OWNER <i>Dr. Wilder</i>		PHONE
	ARCH'T		
	CONT'R <i>Gill Martin</i>		
	VAL. <i>200.00</i>	STORIES <i>2</i>	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joists						Chimneys	
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE	CONDITION OF WORK—REMARKS
9/17/30	<p>Made Partial Inspection. Contractor now installing new galv-iron gutters on roof. Old Shingles to be removed and roof reshingled with new dipped wood shingles now on premises. A. W. Campbell</p>
9/23/30	<p>Reshingling of Roof of Dairy Completed O.K. A. W. Campbell</p>
9/23/30	<p>COMPLETED AND O.K. Alden W. Campbell INSPECTOR</p>