

DATE	CONDITION OF WORK—REMARKS
	Note. This bldg was started before New Bldg Code became effective & Owner failed to take out Permit before "
3/8/27.	1 ST INSP. FORMS. O.K. A. W. Campbell
1/27	2 ND INSP. FRAME O.K. A. W. Campbell
1/27	3 RD INSP. L.A.H INTERIOR O.K. A. W. Campbell
COMPLETED AND O. K.	Inspector