

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | |
|----------------------------|---|
| PERMIT No. <i>A-943</i> | LOCATION <i>South side of Alley 1005-15th Street</i> |
| DATE <i>9/13/33</i> | PURPOSE <i>Remod apartments for lath rooms</i> |
| ZONE <i>Gen Com.</i> | OWNER <i>G. W. Murray</i> |
| | ARCH'T <i>Millsbaugh, Paul & Thomas</i> |
| | CONT-R |

| | | | | |
|------------------|------------------|-------|-------|------|
| VAL. <i>7000</i> | STORIES <i>4</i> | ROOMS | APTS. | SIZE |
|------------------|------------------|-------|-------|------|

| | | | |
|-------------------|--|------------------|--|
| Light Shafts | | Elevator Shafts | |
| Vent Shafts | | Boiler Rooms | |
| Owner's Inspector | | Sprinkler System | |
| Lath | | Gas Vents | |
| Fire Escapes | | Chimneys | |
| Stand Pipes | | Skylights | |

| DATE | CONDITION OF WORK-REMARKS |
|---------|---|
| 9/14/33 | Made Partial Frame Inspection of New Bath Rms being built one above the other for South east Apartments. Will install it for Floor East Apts later A.W. Campbell |
| 9/29/33 | 2 ND /NSP. Frame for New Bath Rm. A.W. Campbell |
| 10/2/33 | 3 RD /NSP. 1st Floor " " " " A.W. Campbell |
| | |
| 10/1/33 | 4 TH /NSP. Toilet & Shower Rm Completed |
| | COMPLETE AND O.K. A.W. Campbell INSPECTOR |