

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-4416-</i>	LOCATION <i>1857 - 43<sup>rd</sup> St.</i>
DATE <i>6/10/36</i>	PURPOSE <i>Erect new dwlg. &amp; garage</i>
ZONE <i>2-Fam</i>	OWNER <i>Mr. B.H. &amp; B.E. Bill</i>
	ARCH'T.
	CONTR. <i>O'Connell</i>

VAL. <i>3000<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE <i>duplex</i>
-------------------------------	---------------------	-------------------	-------	-----------------------

LIGHT SHAFTS	ELEVATOR SHAFTS	<i>99301 @ 350 3400<sup>00</sup></i>
VENT SHAFTS	BOILER ROOMS	
OWNER'S INSPECTOR	SPRINKLER SYSTEM	
LATH	GAS VENTS	
FIRE ESCAPES	CHIMNEYS	
STAND PIPES	SKYLIGHTS	

DATE

CONDITION OF WORK-REMARKS

6/11 36

1<sup>st</sup> Drop Formed OK Rupture

7/29-

2 " Frame " Rupture

COMPLETE  
AND O. K.

INSPECTOR