

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>A-3081</i>		LOCATION <i>3098 - 32nd St</i>			
DATE <i>7/24/3</i>		PURPOSE <i>General repairs upon flat for fire loss.</i>			
ZONE <i>2-Fam Non Conforming</i>		OWNER <i>J.M. Meeder</i>			
ARCH'T <i>F.C. Platenau</i>		CONTR. <i>F.C. Platenau</i>			
VAL. <i>2000⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE	
LIGHT SHAFTS		ELEVATOR SHAFTS			
VENT SHAFTS		BOILER ROOMS			
OWNER'S INSPECTOR		SPRINKLER SYSTEM			
LATH		GAS VENTS			
FIRE ESCAPES		CHIMNEYS			
STAND PIPES		SKYLIGHTS			

DATE	CONDITION OF WORK—REMARKS
8/1/35	2 ND / NSP Frame for Repairs to 2 ND Story of Frame Store & Flat Bldg damaged by fire Burned Timbers replaced with new. O. K. M. Campbell
8/23/35	3 RD / NSP INT. BATH OK M. Campbell
10/15-35	4 " Final OK Rutter
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>