

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-2556</i>	LOCATION <i>1357 - 41st Street -</i>
DATE <i>3/4/35</i>	PURPOSE <i>Alterations & repairs to</i>
ZONE <i>1-FAM.</i>	OWNER <i>dwell. Frank P. Brendek</i>
	ARCH'T <i>W. E. Coffman</i>
	CONT'R <i>Lord & Bishop -</i>

VAL. <i>750⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK-REMARKS
3/1/35	Made Preliminary Insp of Repairs to be made to rear part of No 4 dry rot. A.W. Campbell
4/2/35	1 ST /NSP. Concrete Basement Walls. A.W. Campbell
4/2/35	2 ND /NSP. Frame for 1 ST Sty re-erected. A.W. Campbell
4/9/35	2 ND /NSP " " 2 ND " " " " OK A.W. Campbell
4/11/35	3 RD /NSP. INT. LATH for 2 ND Sty OK A.W. Campbell
4/12/35	3 RD /NSP " " " 1 ST Sty OK A.W. Campbell
4/17/35	3 RD /NSP EXT. LATH FOR ADDITION OK A.W. Campbell
	4 TH /NSP. Alterations & Repairs completed OK
5/25/35	COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR