

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

M-12-30

PERMIT NO. <i>B-20025</i> DATE <i>3-23-49</i> ZONE	LOCATION	<i>408 S Street</i>
	PURPOSE	<i>Repair dwlg.</i>
	OWNER	<i>C. Benicich</i>
	ARCH'T.	
	CONTR.	<i>H. Yamashita</i>

VAL.	<i>\$4000</i>	STORIES	ROOMS	APTS.	SIZE
------	---------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
5/19/49	Farm Insp. (East Wall) D. E. Buckins
6/7/49	" " (North ") "
9/30/49	Lath Insp. "
11/8/50	Final Insp. "
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>