

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11.031</i>	LOCATION <i>1206 - 10th</i>
DATE <i>11/1/43</i>	PURPOSE <i>General repairs - Blinds due to fire</i>
ZONE <i>-</i>	OWNER <i>Fuller Invest. Co.</i>
	ARCH'T.
	CONTR. <i>Frank Maloney</i>

VAL. <i>3500⁰⁰</i>	STORIES <i>-</i>	ROOMS <i>-</i>	APTS. <i>0</i>	SIZE
-------------------------------	---------------------	-------------------	-------------------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
1/12/43	2 ND / N.S.P. Frame for Basement 17 2 ND Street recently damaged by fire. ^{OK} A.W. Campbell
1/14/43	3 RD / N.S.P. INT. L.A.T.A. (3/8" Prot. Lath on Ceiling) Shut Rock on walls. ^{OK} A.W. Campbell
	4 TH / N.S.P. Repairs Completed ^{OK}
1/29/43	COMPLETE AND O. K. <i>Allen W. Campbell</i> INSPECTOR