

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT No. <i>A-882</i>	LOCATION <i>3249 - B Street</i>			
DATE <i>Aug 25th 33</i>	PURPOSE <i>Adding Rm. on side of house</i>			
ZONE <i>V-Fam</i>	OWNER <i>Mrs J. Miller</i>			
	ARCH'T <i>Owner (day work)</i>			
	CONT-R			
VAL. <i>150.00</i>	STORIES	ROOMS	APTS.	SIZE

Light Shafts	Elevator Shafts
Vent Shafts	Boiler Rooms
Owner's Inspector	Sprinkler System
Lath	Gas Vents
Fire Escapes	Chimneys
Stand Pipes	Skylights

DATE	CONDITION OF WORK-REMARKS
8/24/33	1 ST /NSP. PIERS FOR 1-850 RM. ADDITION TO SIDE OF Dwlg. O.K. Ad Campbell
9/8/33	2 ND /NSP. Frame for addition Ad Campbell
9/8/33	3 RD .. Plasterboard walls & ceiling Ad Campbell
9/8/33	4 TH in Addition. Completed wood partition which will be done by owner later
9/8/33	COMPLETE AND O.K. Ad Campbell INSPECTOR