

Lot #301		BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD			\$38.50
Oakmont Terrace		TYPE BUILDINGS		R-79	E264-270
PERMIT NO. D-7666	LOCATION		7224 = 15th Street	A-5	
DATE Jan 30-61	PURPOSE	Const. dwelling & att. garage			
ZONE R-1	OWNER	W. E. Benson 4923 - 42nd St.			
	ARCH'T				
	CONT'R	Owner	GL 5-8541		
VAL.	\$13,475.	STORIES 1	ROOMS 6	APTS.	504-gar. SIZE 1273 sq. ft.
INSP.	DATE	INSPECTOR			
FORM	2-17-61	Burbato			
JOIST	2-28-61	Burbato			
FRAME		Burbato			
LATH	4-5-61	Berry			
FINAL	10-3-61	Berry			

1117  
 1118  
 1119  
 1120  
 1121  
 1122  
 1123  
 1124  
 1125  
 1126  
 1127  
 1128  
 1129  
 1130  
 1131  
 1132  
 1133  
 1134  
 1135  
 1136  
 1137  
 1138  
 1139  
 1140  
 1141  
 1142  
 1143  
 1144  
 1145  
 1146  
 1147  
 1148  
 1149  
 1150  
 1151  
 1152  
 1153  
 1154  
 1155  
 1156  
 1157  
 1158  
 1159  
 1160  
 1161  
 1162  
 1163  
 1164  
 1165  
 1166  
 1167  
 1168  
 1169  
 1170  
 1171  
 1172  
 1173  
 1174  
 1175  
 1176  
 1177  
 1178  
 1179  
 1180  
 1181  
 1182  
 1183  
 1184  
 1185  
 1186  
 1187  
 1188  
 1189  
 1190  
 1191  
 1192  
 1193  
 1194  
 1195  
 1196  
 1197  
 1198  
 1199  
 1200

DATE	SPECIAL CONDITIONS OF WORK—REMARKS
5-5-61	P.V. Tape rest of sheet rock, solid sheathing at ceiling line. Fin. block in garage. <i>Beatty</i>
6-24-61	PT. Final, 1/2 in 5/8 wood in place of 3/8 wood rest in garage. No solid sheathing at ceiling line. <i>Beatty</i>
9-13-61	Hooked. Call Benson. <i>Beatty</i>
10-4-61	Inspection. Call Benson. Benson will call tomorrow afternoon. <i>Beatty</i>
10-18-61	Hooked. End notes. <i>Beatty</i>
	COMPLETE AND OK
	INSPECTOR