

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-28965</i>	LOCATION <i>625-41st</i>
DATE <i>May 15-50</i>	PURPOSE <i>Re-roof</i>
ZONE <i>2</i>	OWNER <i>J. W. Healy</i>
	ARCH'T. <i>J. J. G. O'Connell</i>
	CONTR. <i>Yancey D.</i>

VAL. <i>263⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
------------------------------	---------	-------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	<p data-bbox="343 988 485 1034">COMPLETE AND O. K.</p> <p data-bbox="1301 1005 1450 1028">INSPECTOR</p>