

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <b>B-8213</b>	LOCATION <b>947 - Robertson Way</b>			
DATE <b>5/12/41</b>	PURPOSE <b>2nd fl. new dwlg. &amp; garage</b>			
ZONE <b>—</b>	OWNER <b>Dave Hill Jr.</b>			
	ARCH'T. <b>—</b>			
	CONTR. <b>Dave Hill</b>			
VAL. <b>5000</b>	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	<b>1025<sup>pl</sup></b>
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<b>@.350</b>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
5/12/41	1 <sup>ST</sup> /NSP. Forms in place <sup>OK</sup> HW Campbell
10/16/41	2 <sup>ND</sup> /NSP. Frame " " " " <sup>OK</sup> HW Campbell
	<div style="display: flex; justify-content: space-between;"> <span data-bbox="272 853 396 888">COMPLETE AND O. K.</span> <span data-bbox="1098 868 1229 888">INSPECTOR</span> </div>