

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. —	LOCATION <i>1014 - 75th</i>
DATE <i>11/21/46</i>	PURPOSE <i>Repair Roof</i>
ZONE —	OWNER <i>L. Larson</i>
	ARCH'T.
	CONTR. <i>W. J. Hoff</i>

VAL. <i>90⁰⁰</i>	STORIES <i>1</i>	ROOMS <i>1</i>	APTS.	SIZE
------------------------------------	-------------------------	-----------------------	--------------	-------------

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
	COMPLETE AND O. K.
	INSPECTOR