

1805 2473

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

<b>PERMIT NO.</b>	<b>LOCATION</b> 3801 - 15th Avenue
<b>DATE</b>	<b>PURPOSE</b> Wreck 1-family dwelling
	<b>OWNER</b> Mary Gutierrez 1770 - 59th Avenue
<b>ZONE</b>	<b>ARCH'T</b>
	<b>CONT'R</b>

<b>VAL.</b>		<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
<b>INSP.</b>	<b>DATE</b>	<b>BLDG. TYPE</b>	<b>OCCUPANCY GROUP</b>		<b>PHONE (O) (C)</b>
<b>FORM</b>					
<b>JOIST</b>		Condemned by Building Division			
<b>FRAME</b>					
<b>SHEET ROCK</b>					
<b>FINAL</b>					

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
	<p data-bbox="282 980 431 1045"><b>COMPLETE AND OK</b></p> <p data-bbox="1281 1011 1438 1040"><b>INSPECTOR</b></p>