RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

PROPERTY PARCEL NO.	JOB ADDRESS	INSPECTION AREA
	1119 37th Street	1

LEGAL DESCRIPTION	OCCUP. GR.	CONST TYPE	VAR. NO.	FIRE ZONE

TITLE AND NAME	1/C	ADDRESS	ZIP	CITY LIC. NO.	TEL. NO.
GEN. CONTR.					
ELEC. CONTR.					
PLBG. CONTR.					
MECH. CONTR.					
ARCH. ENGR.					
OWNER					
CONST. LOAN LENDER					

BLDG. WIDTH	BLDG. LENGTH	TOTAL HEIGHT	NO. OF STORIES	ROOF CONSTR.	AREA 1st FLOOR	TOTAL AREA	C.S.D.	C.I. CASE
							CENSUS TRCT. NO.	

SIDE YARDS	REAR YARDS	SET BACK REQ.	USE ZONE	PARK'G REQ.	SPACES	TREES RMVD.	EXISTING BLDG'S SAME LOT	HOW USED

FINAL INSPECTIONS	
BUILDING BY	DATE
ELECTRICAL BY	DATE
PLUMBING BY	DATE
MECHANICAL BY	DATE
CERTIFICATE OF OCCUPANCY	
ISSUED BY	DATE

NATURE OF WORK:-

PERMIT NO. S.P. -	
ISSUED BY	
ISSUANCE DATE	
VALUATION	$
R.D.F. FEE	$
S.M.I. FEE	$
PLAN CK. FEE	$
SEWER INCL. FEE	$
PERMIT FEE	$
	$
	$
TOTAL FEES	$

MICROFILM RECORD

PLANS AND APPLICATION	REEL NO.	FRAME NO:-	TO
INSPECTION RECORD	REEL NO.	FRAME NO:-	TO
JOB FILE	REEL NO.	FRAME NO:-	TO

REMARKS AND/OR VARIANCES

Dwelling

BI-FI-R

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO. M Ch

DATE

ZONE

OCT 5 - 1927

SACRAMENTO BUILDING DIVISION

LOCATION 1119-37th 37 K

PURPOSE Conc Stairs & Basement | ROOMS 1 & Bath | APTS. 1

OWNER E L ROBERTS | PHONE

ARCH'T

CONT'R OWNER

VAL. Less than 100 | STORIES | SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF			
Ex Wall	Joists						Chimneys		Cement Tests
	Beams and Girders						Fire Place		
Int Wall	Studs and Columns						Gas Water Heater		
	Bridging Fire Stops						Heater Closet		
	Fire Escape Stand Pipes						Furnace		Window Courts
Piers	Metal Lath						Boiler Room		
	Stairs						Elevator Shaft		

[redacted]

DATE	CONDITION OF WORK—REMARKS
2/15/27	Stairway from screen porch to basement &c A. L. Campbell Co

COMPLETED AND O. K.

INSPECTOR



BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPES I, II, III, IV, V, VI BUILDINGS

PERMIT NO. 2 ch 7	LOCATION 1119-37 St
DATE 11/1/29	PURPOSE 1-2 Fam Frame Dwl Town
ZONE	PHONES
	OWNER E R Roberts
	ARCH'T
	CONT'R E T Johnson Co

VAL. Ear	STORIES	ROOMS	APTS.	SIZE

Steel Tested by		Elevator Shafts	
Cement Tested by		Boiler Rooms	
Owner's Inspector Rfcd. Conc.		Sprinkler System	
		Floor Tests	
Fire Escapes			
Stand-pipes			

DATE	CONDITION OF WORK—REMARKS

COMPLETED AND O. K.

INSPECTOR