908 44th Street

RECORD OF SUBSEQUENT PERMITS ISSUED

| DATE | TYPE OF PERMIT AND VALUATION | PERMIT NO. AND FEE | NATURE OF WORK | PRESENT OWNER AND ADDRESS | CONTRACTOR & ADDRESS | FINALED BY | DATE |
|---|---|---|---|---|---|---|---|
| 9-1-37 | Bldg. $300 | A-6896 | Reshingle & add rm | H.C. Jacobs | Jospeh Pesce | | |
| 10-5-37 | Bldg. $175. | A-7135 | Reshingle | H.C. Jacobs | Bush Roofing | | |
| 11-22-39 | Bldg. $125. | B-4321 | Enlarge garage | H.C. Jacobs | Owner | | |
| 1-21-70 | Bldg. $600 | G-5579 $10. | Repair pest damage to Dwelling | Berkley Morris | Orhcard Supply | COURT | 1-29-70 |
| 10-13-70 | Bldg. $2,400 | G-8774 $23. | Convert patio into living rm & enclose rear porch of Dwl.g | Harry McDowell | Owner | BARBATO | 11-15-71 |
| 1-27-71 | Bldg. $100 | H-11 $5.00 | Repair pest damage to Dwelling | Harry McDowell | Orhcard Supply | FULLER | 2-5-71 |
| 1-19-76 | M.E.$2,000 | d-307 $25. | Install heat pump system | Harry McDowell | Rick Thompson 5831-9 Rosebud Ln | Cecchettini Collins | 1-26-76 E 1-29-76 M |
| | noplbg-Collins 1-27-76 | J 8545 | | | | | |

MICROFILM RECORD

| PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. | PERMIT NO. | REEL AND FRAME NOS. |
|---|---|---|---|---|---|
| G-5579 | R 274 F 450 | D 307 | R435F172 final | | |
| G-8774 | R 289 F 469 | | | | |
| H-11 | R 295 F 145 | | | | |
| D-307 | R434F054 | | | | |
| A 6896 | R434F054 | | | | |
| A 7135 | R434F054 | | | | |
| B 4321 | R434F054 | | | | |
| G 5579 | R434F054 | | | | |
| G 8774 | R434F054-055 Combine | | | | |
| H-11 | R434F054-055 Combine | | | | |

# RECORD CARD - BUILDING INSPECTIONS DIVISION - CITY OF SACRAMENTO, CALIFORNIA

| PROPERTY PARCEL NO. | JOB ADDRESS | INSPECTION AREA |
|---|---|---|
| | 908 44th Street | 1 |

| LEGAL DESCRIPTION | OCCUP. GR. | CONST TYPE | VAR. NO. | FIRE ZONE |
|---|---|---|---|---|
| | | | | |

| TITLE AND NAME | 1/C | ADDRESS | ZIP | CITY LIC. NO. | TEL. NO. |
|---|---|---|---|---|---|
| GEN. CONTR. Owner | | | | | |
| ELEC. CONTR. | | | | | |
| PLBG. CONTR. | | | | | |
| MECH. CONTR. | | | | | |
| ARCH. ENGR. | | | - | | |
| OWNER E.V. Gilkey | | | | | |
| CONST. LOAN LENDER | | | | | |

| BLDG. WIDTH | BLDG. LENGTH | TOTAL HEIGHT | NO. OF STORIES | ROOF CONSTR. | AREA 1st FLOOR | TOTAL AREA | C.S.D. | C.I. CASE |
|---|---|---|---|---|---|---|---|---|
| | | | | | | | CENSUS TRCT. NO. | |

| SIDE YARDS | REAR YARDS | SET BACK REQ. | USE ZONE | PARK'G REQ. | SPACES | TREES RMVD. | EXISTING BLDG'S SAME LOT | HOW USED |
|---|---|---|---|---|---|---|---|---|
| | | | | | | | | |

NATURE OF WORK:- Frame Stucco, 1 sty & garage

| | |
|---|---|
| PERMIT NO. S.P. - | 7830 |
| ISSUED BY | |
| ISSUANCE DATE | 4-12-24 |
| VALUATION | $ |
| R.D.F. FEE | $ |
| S.M.I. FEE | $ |
| PLAN CK. FEE | $ |
| SEWER INCL. FEE | $ |
| PERMIT FEE | $ |
| | $ |
| | $ |
| TOTAL FEES | $ |

## MICROFILM RECORD

| | | | |
|---|---|---|---|
| PLANS AND APPLICATION | REEL NO. R434F056 | FRAME NO:- 05 | Complete |
| INSPECTION RECORD | REEL NO. ~ | FRAME NO:- | TO |
| JOB FILE | REEL NO. | FRAME NO:- | TO |

REMARKS AND/OR VARIANCES

| FINAL INSPECTIONS | |
|---|---|
| BUILDING BY | DATE |
| | |
| ELECTRICAL BY | DATE |
| | |
| PLUMBING BY | DATE |
| | |
| MECHANICAL BY | DATE |
| | |
| CERTIFICATE OF OCCUPANCY | |
| ISSUED BY | DATE |
| | |

BI-FI-R