

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>8978</i>	LOCATION <i>4416 F St.</i>
DATE <i>12/17/31</i>	PURPOSE <i>Bldg for Pm' Garage</i>
OWNER <i>Helen M Watson</i>	PHONES
ZONE <i>2 Jam</i>	ARCH'T
CONT-R <i>Owner</i>	

VAL. <i>250 -</i>	STORIES	ROOMS	APTS.	SIZE <i>17 x 18</i>
-------------------	---------	-------	-------	------------------------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
1/19/32	Inspected Private Garage built by owner on rear of lot. Same completed O.K. Work now suspended.
	not in order with labor. Sheardes called again &
	built small breakfast room addition on rear of Dwyer
	Told him he could do said additional work
	under this permit. As mentioned, the valuation
	of the permit is 100.00 which he would have been
	required to do it when he took out the permit.
2/24/32	4 <sup>th</sup> N.S.P. Pri. Garage. Add. for Breakfast Room & Rerhinging
	of Roof of Dwyer Completed O.K.
2/24/32	COMPLETE AND O. K. <i>Asst Campbell</i> INSPECTOR