

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE VII BUILDINGS

PERMIT NO.	LOCATION 3318 N St. EAST SAC TO TRACT.		
<i>No Charge</i>	PURPOSE	ROOMS	APTS.
DATE	Gen. Rep. to Roof of Duly		
<i>1/4/28</i>	OWNER	PHONE	
ZONE	MRS. A. BROWN		
<i>2ND RES</i>	ARCH'T		
	CONTR	OWNER	
	VAL. 50 ⁰⁰	STORIES	SIZE

FOUNDATION	STORY	BSMT	1	2	3	ROOF		
Ex Wall	Joints						Chimneys	Cement Tests
	Beams and Girders						Fire Place	
Int Wall	Studs and Columns						Gas Water Heater	
	Bridging Fire Stops						Heater Closet	
Piers	Fire Escape Stand Pipes						Furnace	Window Courts
	Metal Lath						Boiler Room	
	Stairs						Elevator Shaft	

DATE

CONDITION OF WORK—REMARKS

4/4/28

General Repairs to Roof of Dory. A. W. Campbell

4/4/28

COMPLETED
AND O. K.

Alden W. Campbell

INSPECTOR