

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-47739</i>	LOCATION <i>722 - K St.</i>			
DATE <i>3/17/41</i>	PURPOSE <i>Remodel interior Bldg.</i>			
ZONE	OWNER <i>W. T. Grant Inc.</i>			
	ARCH'T.			
	CONTR. <i>O. Peterson</i>			
VAL. <i>1300</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
3/20/21	2 ND / HSP. Framing. Remains in place on 2 ND floor of Greenfield. [unclear]
	<p>COMPLETE AND O. K.</p> <p style="text-align: right;">INSPECTOR</p>

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-4739</i>	LOCATION <i>722 - K St.</i>			
DATE <i>3/17/41</i>	PURPOSE <i>Remodel interior bldg.</i>			
ZONE	OWNER <i>W. T. Grant Inc.</i>			
	ARCH'T.			
	CONTR. <i>O. Peterson</i>			
VAL. <i>1300</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK-REMARKS
3/20/41	2 ND / ASP. From J. R. ... on 2 ND ...
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>