

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>B-5244</i>		LOCATION <i>1783 - 10<sup>th</sup> Ave</i>			
DATE <i>5/6/38</i>		PURPOSE <i>Erect new dwlg.</i>			
ZONE <i>1-Fam</i>		OWNER <i>C. C. Ruby</i>			
		ARCH'T.			
		CONTR. <i>Owner</i>			
VAL.	<i>5000</i>	STORIES <i>2</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>area</i>		
VENT SHAFTS		BOILER ROOMS	<i>1924<sup>sq</sup></i>		
OWNER'S INSPECTOR		SPRINKLER SYSTEM			
LATH		GAS VENTS			
FIRE ESCAPES		CHIMNEYS			
STAND PIPES		SKYLIGHTS			

DATE	CONDITION OF WORK—REMARKS
5/9/38	1 <sup>ST</sup> INSP. Form in place <sup>OK</sup> All complete
5/27/38	2 <sup>ND</sup> INSP. Form in place <sup>OK</sup> All complete
6/1/38	3 <sup>RD</sup> INSP. INT & EXT WORK <sup>OK</sup> All complete
	<p data-bbox="311 881 433 919">COMPLETE AND O. K.</p> <p data-bbox="1147 897 1282 919">INSPECTOR</p>