

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | | |
|-------------------------------|--|-------|-------|------|
| PERMIT NO. <i>B-12944</i> | LOCATION <i>507-39th St.</i> | | | |
| DATE <i>11/22/44</i> | PURPOSE <i>Make addn to rear of bldg.</i> | | | |
| ZONE | OWNER <i>Fred Cornacchioli</i> | | | |
| | ARCH'T. | | | |
| | CONTR. <i>Owner</i> | | | |
| VAL. <i>2000⁰⁰</i> | STORIES | ROOMS | APTS. | SIZE |

| | |
|-------------------|------------------|
| LIGHT SHAFTS | ELEVATOR SHAFTS |
| VENT SHAFTS | BOILER ROOMS |
| OWNER'S INSPECTOR | SPRINKLER SYSTEM |
| LATH | GAS VENTS |
| FIRE ESCAPES | CHIMNEYS |
| STAND PIPES | SKYLIGHTS |

| DATE | CONDITION OF WORK-REMARKS |
|-----------------------|---|
| 11/30/44 | 1 ST /NSP. Fences In Addition to rear of Duly. O. K. M. Campbell |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| COMPLETE AND O. K. | INSPECTOR |