

**BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD**

**TYPE BUILDINGS**

<b>PERMIT NO.</b> 8676	<b>LOCATION</b>	1073-51 <sup>1/2</sup> St
<b>DATE</b> 10/1/31	<b>PURPOSE</b> RENOV	<b>PHONES</b>
<b>ZONE</b> 2 Fam	<b>OWNER</b> H A Hansen	
	<b>ARCH'T</b>	
	<b>CONT-R</b> Baron G... ..	

<b>VAL.</b> 100	<b>STORIES</b>	<b>ROOMS</b>	<b>APTS.</b>	<b>SIZE</b>
--------------------	----------------	--------------	--------------	-------------

<b>Light Shafts</b>		<b>Elevator Shafts</b>	
<b>Vent Shafts</b>		<b>Boiler Rooms</b>	
<b>Owner's Inspector</b>		<b>Sprinkler System</b>	
<b>Lath</b>		<b>Gas Vents</b>	
<b>Fire Escapes</b>		<b>Chimneys</b>	
<b>Stand Pipes</b>		<b>Skylights</b>	

DATE

CONDITION OF WORK-REMARKS

10/20/31

Re Roofing 7 Dwg with Compositors  
Shingles. Completed

10/20/31

COMPLETE  
AND O.K.

Alden W Campbell

INSPECTOR