

*R311 E440*

**BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD**

\$18.00

**TYPE BUILDINGS**

PERMIT NO.					
H-3374		LOCATION 3774 - 6th Avenue A-1 (27)			
DATE		PURPOSE Repair fire damage to dwelling			
Sept. 22-71		OWNER Robert Lurry Same			
ZONE		ARCH'T			
R-1		CONT'R Petersen & Assoc. 1800 - 27th St.			
VAL. \$1,500.		STORIES	ROOMS	APTS.	SIZE
INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C) 452 3131	
FORM					
JOIST					
FRAME					
SHEET ROCK					
FINAL	10-13-71	<i>J. M. ...</i>			

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|------|--------------------------------------|
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      |                                      |
|      | <b>COMPLETE<br/>AND OK</b>           |
|      | <b>INSPECTOR</b>                     |