

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-1009</i>	LOCATION <i>1901 - Markham Way</i>			
DATE <i>7/11/38</i>	PURPOSE <i>New dwlg. garage</i>			
ZONE <i>2 - Zone</i>	OWNER <i>Geo. J. Weston</i>			
	ARCH'T. <i>C</i>			
	CONT'R. <i>Owner</i>			
VAL. <i>4500</i>	STORIES <i>1</i>	ROOMS <i>5</i>	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS			BOILER ROOMS	<i>1120¹⁰'</i>
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
7/12/38	1 ST / NSP. Form in place ^{OK} R. W. Campbell
8/1/38	2 ND / NSP. Form in place ^{OK} R. W. Campbell
9/15/38	3 RD / NSP. 1st & 2nd LATH ^{OK} R. W. Campbell
	<p data-bbox="294 840 422 881">COMPLETE AND O. K.</p> <p data-bbox="1140 855 1273 878">INSPECTOR</p>