

Miller

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

\$11.00

TYPE BUILDINGS

*R 84
E 383*

PERMIT NO. D-8684	LOCATION 1905 - G Street	A-2
DATE Jun 1-61	PURPOSE Remodel 4-Unit Apartment House.	
ZONE C-4	OWNER E. J. Miller	309-ChennaultCrt. D.P.
	ARCH'T	
	CONT'R Owner	Same WA 5-4253

VAL. \$3,000.	STORIES 2	ROOMS	APTS.	SIZE
---------------	--------------	-------	-------	------

INSP.	DATE	INSPECTOR
FORM		
JOIST	<i>7-18-61</i>	<i>Fulley</i>
FRAME	<i>7-18-61</i>	<i>Fulley</i>
LATH	<i>7-24-61</i>	<i>Jones & 29-61 Hall SR Fulley</i>
FINAL	<i>10-15-61</i>	<i>[Signature]</i>

DATE

SPECIAL CONDITIONS OF WORK—REMARKS

10-25-61 Pt Trial Gitters, sand rats, S.C.
 Doors in Hallways? Not ready. SF 11-9-61 ^{Feller}

11-14-61 Pt Trial: Doors opening into Hallways
 are not solid core. No gitters. Feller

1-29-62 SF 2-1-62 Barbuto

4-30-62 SF 5-11-62 All items not completed Barbuto

5-11-62 SF 7-11-62 Barbuto

7-12-62 SF 8-12-62 Count

8-12-62 SF 9-13-62 Count

9-13-62 Not completed Count

10-15-62

COMPLETE
AND OK

INSPECTOR