

BUILDING DIVISION-BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

| | | | | |
|-------------------------------|--|------------------|-------|------|
| PERMIT NO. <i>B-13413-</i> | LOCATION <i>3045-39th St.</i> | | | |
| DATE <i>5/3/45</i> | PURPOSE <i>Add Bed Rm. to rear of dwlg.</i> | | | |
| ZONE | OWNER <i>P. A. Norris</i> | | | |
| | ARCH'T. | | | |
| | CONTR. <i>Owner</i> | | | |
| VAL. <i>8000</i> | STORIES | ROOMS | APTS. | SIZE |
| LIGHT SHAFTS | | ELEVATOR SHAFTS | | |
| VENT SHAFTS | | BOILER ROOMS | | |
| OWNER'S INSPECTOR | | SPRINKLER SYSTEM | | |
| LATH | | GAS VENTS | | |
| FIRE ESCAPES | | CHIMNEYS | | |
| STAND PIPES | | SKYLIGHTS | | |

| DATE. | CONDITION OF WORK—REMARKS |
|---------|--|
| 5/31/45 | Made location inspection for work to be built on rear for 2 nd story of 1 story Dory O.K. A.W. Campbell |
| 6/25/45 | 2 nd floor. Frame for above. A.W. Campbell 3 rd floor. Rock Lath & Plaster. |
| | |
| | |
| | |
| | |
| | |
| | <p data-bbox="348 837 480 878">COMPLETE AND O. K.</p> <p data-bbox="1229 862 1367 883">INSPECTOR</p> |