

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10809</i>	LOCATION <i>1616 - 15th St.</i>
DATE <i>10/23/42</i>	PURPOSE <i>Remodel. flats.</i>
ZONE	OWNER <i>W. J. Guines</i>
	ARCH'T.
	CONTR. <i>Owner</i>

VAL <i>750⁰⁰</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS		
VENT SHAFTS		BOILER ROOMS		
OWNER'S INSPECTOR		SPRINKLER SYSTEM		
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE.	CONDITION OF WORK-REMARKS
12/3/42	General Alterations and Repairs to remodel Dwyer into 4 Apartments
	Completed O.K.
	A.W. Campbell
	
	
	
	
	
12/3/42	COMPLETE AND O. K. A.W. Campbell
	INSPECTOR