

## BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

## TYPE BUILDINGS

PERMIT NO. <i>15-3485</i>	LOCATION <i>1061 - Tenneight Way.</i>			
DATE <i>7/20/39</i>	PURPOSE <i>New dwlg. and</i>			
ZONE <i>-</i>	OWNER <i>Bella &amp; Esthman</i>			
	ARCH'T. <i>Hadley &amp; Hadley</i>			
	CONT'R. <i>Hadley &amp; Hadley</i>			
VAL. <i>5000<sup>00</sup></i>	STORIES <i>1</i>	ROOMS <i>6</i>	APTS.	SIZE
LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>	
VENT SHAFTS		BOILER ROOMS	<i>1270'</i>	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 350'</i>	
LATH		GAS VENTS		
FIRE ESCAPES		CHIMNEYS		
STAND PIPES		SKYLIGHTS		

DATE	CONDITION OF WORK--REMARKS
7/25/39	1 <sup>ST</sup> INSP. Forms in place <sup>OK</sup> W. Campbell
8/8-39	2 <sup>ND</sup> " Frame " " " " "
8/15/39	3 <sup>RD</sup> INSP. INT. & EXT. WORK <sup>OK</sup> W. Campbell
9/28/39	4 <sup>TH</sup> INSP. Dwg & Garage Complete
" " "	Issued Final Insp. & Cert. of Occupancy.
	Street Cleaned up OK
7/28/39	COMPLETE AND O. K. <i>W. Campbell</i> INSPECTOR