

Q173 150-54

Por. Lot 187 **BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD** \$64.00

Colonial Acres **TYPE BUILDINGS** *B175 → 600-601 St. W. 187*

PERMIT NO.	LOCATION	3991 - 71st Street	A-4
E-1101	PURPOSE	Const. dwlg. & att. gar. & covered patio	
DATE	OWNER	Richard R. Carrington 3931-71st St.	
July 12-65	ARCH'T		
ZONE	CONT'R	Owner same 451-5316	
R-1			

VAL. \$18,700.	STORIES	ROOMS	APTS.	506-gar.	SIZE
				1880 sq. Ft.	

INSP.	DATE	BLDG. TYPE	OCCUPANCY GROUP	PHONE (O) (C)
FORM	9-1-65	Fuller		
JOIST	9-30-65	Barbato		
FRAME	5-6-66	Fuller		
SHEET ROCK	5-24-66	Chapin		
FINAL	1-27-67	Larsen		

DATE	SPECIAL CONDITIONS OF WORK — REMARKS
5-3-66	Pt Dam - Need corr. girts @ 24' O.C. & blocking around girts at furnace. No 2x7 diagonal wall braces in garage. Block 5" high around furnace vent Chapman
5-23-66	Pt SR - Factory edge of SR must be down at tub. Repair hole in SR at shown! Chapman
1-12-67	Cut out wood around vent in road Loren
	COMPLETE AND OK INSPECTOR

2025 RELEASE UNDER E.O. 14176