

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>9260</i>	LOCATION <i>2718 29</i>
DATE <i>3/21/32</i>	PURPOSE <i>Make In Rch Under Foundation</i>
OWNER <i>Walter J. ...</i>	PHONES
ZONE	ARCH'T
CONT-R <i>...</i>	

VAL. <i>500</i>	STORIES <i>2</i>	ROOMS	APTS.	SIZE
--------------------	---------------------	-------	-------	------

Light Shafts		Elevator Shafts	
Vent Shafts		Boiler Rooms	
Owner's Inspector		Sprinkler System	
Lath		Gas Vents	
Fire Escapes		Chimneys	
Stand Pipes		Skylights	

DATE	CONDITION OF WORK--REMARKS
3/21/32	1 st /INSP. Forms for increasing size of concrete foundation for Rebars & 7 th day. A.W. Campbell
3/31/32	2 nd /INSP. Frame for new first floor. A.W. Campbell
	3 rd /INSP. Int. Lath & Plastering for Patchwork interior walls & ceiling. A.W. Campbell
4/19/32	4 th /INSP. Remodeling & Repairs & Dry. Completed
4/19/32	COMPLETE AND O. K. <i>Alfred W. Campbell</i> INSPECTOR