

BUILDING DIVISION--BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-11804-</i>	LOCATION <i>528 - Capital Ave</i>			
DATE <i>12/6/43-</i>	PURPOSE <i>General repairs to Bldg.</i>			
ZONE	OWNER <i>Jackson</i>			
	ARCH'T.			
	CONTR. <i>Bingham Const. Co.</i>			
VAL. <i>15000</i>	STORIES	ROOMS	APTS.	SIZE
LIGHT SHAFTS			ELEVATOR SHAFTS	
VENT SHAFTS			BOILER ROOMS	
OWNER'S INSPECTOR			SPRINKLER SYSTEM	
LATH			GAS VENTS	
FIRE ESCAPES			CHIMNEYS	
STAND PIPES			SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
12/7/43	2 ND / H.S.P. Frame for Interior Alterations and Repairs to Restaurant & Cafe
	J. K. A.W. Campbell
	COMPLETE AND O. K. INSPECTOR