

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B-10754</i>	LOCATION <i>(REAR) 1550 - 77th Street 49 ST. TH</i>				
DATE <i>9/28/42</i>	PURPOSE <i>Repairs to understructure of Dolly</i>				
ZONE	OWNER <i>W. Hoeger</i>				
	ARCH'T.				
	CONTR. <i>Owner</i>				
VAL. <i>2000</i>	500 ⁰⁰	STORIES	ROOMS	APTS.	SIZE

LIGHT SHAFTS	<i>Raised Valuation with Owner's consent to include additional work & materials</i>	ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR	<i>W. Campbell 1/28/43</i>	SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

