

R308 F46

BUILDING DIVISION — BUILDING INSPECTOR'S REPORT CARD \$10.00

TYPE BUILDINGS

| | |
|-----------------------------|---|
| PERMIT NO. G-4582 | LOCATION 2541 - 52nd Street A-1 (17) |
| DATE Sep. 4-69 | PURPOSE Repair rot damage to dwelling |
| ZONE R-1 | OWNER S. Kurtz c/o 4709 - Manzanita |
| | ARCH'T 452-6655 |
| | CONT'R Paramount Pest Control 6405-Elvas |

| | | | | |
|--------------------|----------------|--------------|--------------|---------------------------|
| VAL. \$700. | STORIES | ROOMS | APTS. | Avenue SIZE |
|--------------------|----------------|--------------|--------------|---------------------------|

| INSP. | DATE | BLDG. TYPE | OCCUPANCY GROUP | PHONE (O) (C) |
|-------------------|----------------|---------------------|------------------------|----------------------|
| FORM | <i>9-16-69</i> | <i>Barbuto</i> | <i>9-17-69</i> | <i>Miller</i> |
| JOIST | | | | |
| FRAME | <i>9-16-69</i> | <i>Barbuto</i> | | |
| SHEET ROCK | | | | |
| FINAL | <i>7-29-70</i> | <i>Mr. Callaway</i> | | |

| DATE | SPECIAL CONDITIONS OF WORK — REMARKS |
|---------|--------------------------------------|
| 9-16-69 | Airport fuel intake side |
| | good no permit on record |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | COMPLETE AND OK |

INSPECTOR