

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>H-5376</i>	LOCATION <i>2100 - M St.</i>
DATE <i>12/11/36</i>	PURPOSE <i>Alterations & repairs Box</i>
ZONE	OWNER <i>Henderson</i>
	ARCHT.
	CONTR. <i>Roof Sew. Co. 1900 - St. Pk</i>

VAL. *16000*STORIES *1*

ROOMS

APTS.

SIZE

LIGHT SHAFTS		ELEVATOR SHAFTS	
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK-REMARKS
COMPLETE AND O. K.	INSPECTOR