

BUILDING DIVISION—BUILDING INSPECTOR'S REPORT CARD

TYPE BUILDINGS

PERMIT NO. <i>B 5455</i> DATE <i>6/11/41</i> ZONE	LOCATION	<i>933-54th St.</i>
	PURPOSE	<i>Erect new dwlg. for</i>
	OWNER	<i>Tony Brasil.</i>
	ARCH'T.	
	CONTR.	<i>Owner</i>

VAL. <i>4800⁰⁰:-</i>	STORIES <i>—</i>	ROOMS <i>5</i>	APTS.	SIZE
---------------------------------	---------------------	-------------------	-------	------

LIGHT SHAFTS		ELEVATOR SHAFTS	<i>Area</i>
VENT SHAFTS		BOILER ROOMS	
OWNER'S INSPECTOR		SPRINKLER SYSTEM	<i>@ 350</i>
LATH		GAS VENTS	
FIRE ESCAPES		CHIMNEYS	
STAND PIPES		SKYLIGHTS	

DATE	CONDITION OF WORK—REMARKS
6/11-41	1st Insp Terms of Quit
7/14-41	2 " Found " Quit
	<div style="display: flex; justify-content: space-between;"> COMPLETE AND O. K. INSPECTOR </div>